

Message (Digitally Signed)

From: Roddy, Elizabeth A CIV USN NAVFAC SW SAN CA (USA) [elizabeth.rodgy@navy.mil]
Sent: 5/11/2021 11:55:57 PM
To: Praskins, Wayne [Praskins.Wayne@epa.gov]; juanita.bacey@dtsc.ca.gov; Han, Terry@CDPH [terry.han@cdph.ca.gov]
CC: Stoick, Paul T CIV USN NAVFAC SW SAN CA (USA) [paul.stoick@navy.mil]
Subject: Parcel G TU-79 Sr-90 Results
Attachments: J40475-1 Soil Analytical Report_TU79.pdf; J40475-2 Sample HPPG-ESU-TU079A-001 with 4 Additional Aliquots_TU79.pdf; smime.p7s

All,

As promised attached you will find the lab data package for TU-124. The systematic samples are included in J40475-1 and the Sr-90 result for systematic sample -001 is shown on Page 14. The data for the four additional aliquots are included in J40475-2.

As discussed a complete RSY Data Package will be submitted once pending removal boundary soil sample's analytical results are available.

Very Respectfully,

Liz Roddy
Remedial Project Manager
NAVFAC BRAC PMO West
33000 Nixie Way
Bldg. 50, Floor 2
San Diego, CA 92147
(619) 524-5755
elizabeth.rodgy@navy.mil